

PRODUCT INFORMATIONEN
.....**COMPLEMENTARY EQUIPMENT****PIAB load measuring
equipment**
.....

Shows you the limits...

A selection ...




LL Link
with remote display for robust use,
measuring range 0-2,000 kg to
0-75,000 kg



Dynamometer
Measuring range 0-250 kg to 0-50,000 kg,
optionally with remote display



Digital crane scale
Measuring range 2,000 kg to 10,000 kg





Overload guard LKV
with remote display, maximum switching
value 1,000 kgf to 16,000 kgf,
for line dimension 5-8mm to 40-44mm

PIAB

Precision instruments for
measurement, control and
examination of traction forces,
prevent overloading. For use
with rope connectors or other
force transmitters.

i MORE...

This is just a brief presentation of a whole
range of products. Details needed? Ask us.
We provide all the information you need.



And more ...

Applications...

